

2008 Sidewalk Program

Inspection Report


Lot #	Address #:	Description
405	24 Forest Ridge Court	ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
403	33 Forest Ridge Court	3 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. ONE BLOCK IS CHIPPED AND REQUIRES REPLACEMENT.
406	36 Forest Ridge Court	ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
402	47 Forest Ridge Court	2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
407	50 Forest Ridge Court	ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES REPLACEMENT.
408	62 Forest Ridge Court	2 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE LEVELING. ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES REPLACEMENT.
400	71 Forest Ridge Court	3 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
409	78 Forest Ridge Court	4 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
399	83 Forest Ridge Court	3 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
412	87 Olentangy Ridge Place	3 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT.
398	95 Forest Ridge Court	ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES REPLACEMENT.
411	105 Olentangy Ridge Place	ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES LEVELING.
382	106 Olentangy Ridge Place	ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES REPLACEMENT. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE LEVELING.
397	107 Forest Ridge Court	ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES LEVELING. 4 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
396	117 Olentangy Ridge Place	4 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. ONE BLOCK IS CHIPPED AND REQUIRES REPLACEMENT.



2008 Sidewalk Program

Inspection Report

Lot #	Address #:	Description
383	120 Olentangy Ridge Place	2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
410	121 Olentangy Ridge Place	3 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT.
395	129 Meadow Ridge Court	4 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT. ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES LEVELING. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT.
384	130 Olentangy Ridge Place	2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. 2 BLOCKS ARE SPALLED AND REQUIRE REPLACEMENT.
385	144 Meadow Ridge Court	ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. 4 BLOCKS ARE SPALLED AND REQUIRE REPLACEMENT.
394	147 Meadow Ridge Court	ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT.
386	156 Meadow Ridge Court	ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES LEVELING.
393	159 Meadow Ridge Court	3 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT.
387	168 Meadow Ridge Court	2 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT. ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES LEVELING. ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES REPLACEMENT.
392	171 Meadow Ridge Court	4 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT.
388	180 Meadow Ridge Court	3 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT. ONE BLOCK IS CHIPPED AND REQUIRES REPLACEMENT.
391	181 Meadow Ridge Court	2 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT.
390	191 Meadow Ridge Court	4 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT.
389	192 Meadow Ridge Court	ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT.



2008 Sidewalk Program

Inspection Report

Lot #	Address #:	Description
566	214 Beech Trail Court	3 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT. ONE BLOCK HAS HOLES AND REQUIRES REPLACEMENT.
565	225 Beech Trail Court	2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE LEVELING. ONE BLOCK HAS A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRES REPLACEMENT. ONE BLOCK IS CHIPPED AND REQUIRES REPLACEMENT. ONE BLOCK IS SPALLED AND REQUIRES REPLACEMENT.
567	226 Beech Trail Court	ONE BLOCK HAS HOLES AND REQUIRES REPLACEMENT.
569	250 Beech Trail Court	2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. 2 BLOCKS ARE SPALLED AND REQUIRE REPLACEMENT.
570	262 Beech Trail Court	2 BLOCKS ARE CRACKED AND REQUIRE REPLACEMENT. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE LEVELING.
563	271 Beech Trail Court	2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE REPLACEMENT. ONE BLOCK IS CHIPPED AND REQUIRES REPLACEMENT.
571	274 Beech Trail Court	ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT.
562	285 Beech Trail Court	ONE BLOCK IS CRACKED AND REQUIRES REPLACEMENT. 2 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE LEVELING.
572	286 Beech Trail Court	5 BLOCKS HAVE A VERTICAL SEPARATION OF 1/4" OR MORE AND REQUIRE LEVELING.